

U. S. Department of Agriculture

FOREST SERVICE

123

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 Mer.

Corner common to Sections

8, 9, 16, and 17

Corner consists of a 2 sidestake (not) in place



State condition poor

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? The writing on state is in pencil it is a very old F.S. cor.

A. Friesen


(Signature)

10/18/35 (Date)

J-9 Y

Corner again.
 This cot. is located
 N. 87° 30' W. (using 70' dist.)
 40.20 chs. W. of G.L.O. cot.

Metal Location Poster is on a
 tree 3 inches diameter, on the
 side of tree
 from which this Corner bears
 N 29° E
 0.19 chains distant.
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. 5th P. Mer.

Sec. Corner common to Sections
8, 9, 16, and 17



Corner consists of a sq. stake (not) in place
State condition _____

Dimensions above ground 16" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam

Diameter 5"

Bearing S87E

Distance 501Ks

Do you believe this to be a genuine Land Office Corner? ?

If not, why? Only one possible B.T. found. No scribbling found on it. Due possibly to excessive chopping out.

J.C. Leadbeater

(Signature)

Nov. 23/27
(Date)


Forest Ranger
(Title)

U.S. Department of the Interior
Bureau of Land Management
Washington, D.C. 20250

COMMISSIONER OF THE BUREAU OF LAND MANAGEMENT
WASHINGTON, D.C. 20250

Corner agrees:
Give any further facts which will aid in finding this
chain distant.

Metal Location Poster is on a
4 inches diameter, on the East
side of
From which this Corner bears
338M



U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 S. 7⁴ Mer.S. e. c. Corner common to Sections
8, 9, 16, and 17Corner consists of a Squared Stake (not) in place
State condition

Dimensions above ground 16" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

Obliterated			

Species *Tax*

Diameter 5"

Bearing S 84° E

Distance 50 lks

Do you believe this to be a genuine Land Office Corner? ?

If not, why? Only one possible B.T.
found, No scribing found on it,
due possibly to excessive chopping out.

John C. Leadbeater

(Signature)

Forest Ranger

(Title)

Mar. 23, 1929

(Date)

line from ~~south~~ corner
south well cut out for several
chains.

Corner again.

Give any further facts which will aid in finding this


11 hrs. ~~observed~~ distant.

from which this Corner bears S 38° W.

side of ~~Tree~~

tree 4 inches diameter, on the East

Metal Location Poster is on a ~~Tree~~



(Make sketch of topography near Corner)

T. 144 R. 26 Mer. 5+4

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 S. 5th Mer.S. e. c. Corner common to Sections
8, 9, 16, and 17Corner consists of a Squared Stake (not) in place
State condition

Dimensions above ground 16" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

Obliterated			


Species TaxusDiameter 5"Bearing S. 84° EDistance 50 lksDo you believe this to be a genuine Land Office Corner? ?If not, why? Only one possible B.T. found, No scribing found on it, due possibly to excessive chopping out.John C. Leadbeater

(Signature)

Mar. 23, 1927
(Date)Forest Ranger.
(Title)

Corner again.
line from ~~South~~ corner
south well cut out for several
chains.

Give any further facts which will aid in finding this
11 lks. chains distant.
from which this corner bears S. 38° W.
side of tree
tree 4 inches diameter, on the East
Metal Location Poster is on a
T.M.



(Make sketch of topography near corner)