

U. S. Department of Agriculture  
FOREST SERVICE

123

N-13 P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 26 W 5 th. Mer.

Section Corner common to Sections  
15, 16, 21, and 22

Corner consists of a Wood stake (not) in place  
State condition fair

Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

T 144 R 26 S 16	T 144 R 26 S 21	T 144 R 26 S 22	T 144 R 26 S 15
-----------------------	-----------------------	-----------------------	-----------------------

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

FSLP			

Species Oak

Diameter 8"

Bearing N. 42. E

Distance 10 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

*E. Gordon*

(Signature)

Chief of Party E.H.

(Date)

(Title)

N-13

X

Dotted lines for writing notes.

Corner again.

Give any further facts which will aid in finding this


NO chains distant.

from which this Corner bears S 42 W

side of said tree

tree 8" inches diameter, on the south west

Metal Location Poster is on a Oak



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

N-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. Mer.

Sec. 15, 16, 21, and 22 Corner common to Sections

Corner consists of a (not) in place

State condition New treated post

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Diagram for cardinal position with four vertical columns.

N W S E

Diagram for diagonal position with four vertical columns.

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Grid of eight boxes for sketching bearing trees and rocks.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Ray W. Jansett (Signature) Sept 1953 (Date)

(Date)

(Title)

N-13

Ch... ..


Corner again. Set treated post 7" by 3 1/2 feet tall and scribbled "50". It is 0.15 ch. east of old woods roads. Corner is at original G.L.O. location as remains of original blurb B.T. were found. Put up new F.S.L.P. but failed to note direction.

Give any further facts which will aid in finding this chains distant.

from which this Corner bears side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

N-13



Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. Mer. Sec.  
Corner common to Sections  
15, 16, 21, and 22

Corner consists of a \_\_\_\_\_ (not) in place  
State condition New treated post

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner?

If not, why? \_\_\_\_\_

Fasset

(Signature)


13

(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again. Set treated post 4" by 3/4 feet tall and marked "S0". It is 0.15 ch. east of old woods roads. Corner is at original O.L.O. location as remains of original path B-I, were found. Put up new F.S.L.P. but failed to note direction.

Original O.L.O. location as remains of original path B-I, were found. Put up new F.S.L.P. but failed to note direction.



(Make sketch of topography near Corner)