

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. Mer.



Section _____ Corner common to Sections
3, and 4

Corner consists of a _____ (not) in place
State condition New treated post

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No.

If not, why? F. S. established

Ray W Fassett
(Signature)
Sept 1953
(Date)

(Date)

(Title)

Corner is marked by treated post scribed
"PSSO 3/4" at north base of R.R. #111 and
about 1/2 chain south of telephone pole
No. 4129. PSIP tag on pole 4129. Both
tag and corner are visible from U.S. Hwy.
No. 2.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 N. R. 26 W.

Mer.

U. S. Department of Agriculture
FOREST SERVICE

A-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. Mer.

Section Corner common to Sections

3, and 4

Corner consists of a _____ (not) in place



State condition New treated post

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? P. S. established

Fassett

(Signature)

53
(Date)

(Title)

Corner is marked by treated post scribbled
 "1890 3/4" at north base of R.R. 1111 and
 about 1/2 chain south of telephone pole
 No. 4129. TSP tag on pole 4129. Both
 tag and corner are visible from U.S. Hwy.
 No. 2.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

11-23-24
A-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 5th Mer.

Sec. Corner common to Sections
3, and 4

Corner consists of a (not) in place
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? NO

If not, why? This point designated by
Ranger Soderback to be the
Correct position

Edward Iversen


(Signature)

Estimator

(Title)

8/12/29
(Date)

Corner again.
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of **CORNER Stake**
 tree inches diameter, on the S.W.
 Metal Location Poster is on a **Telegraph Pole**



(Make sketch of topography near Corner)

J. J. R. 26 R. 5th Mer.