

Form 874-0—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

N 15  
12-18-33  
12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 26 5<sup>th</sup> Mer.

1/4 Corner common to Sections  
15, and 22

Corner consists of a Burned Stake (not) in place  
State condition

Dimensions above ground 2" x 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species TAM. TAM.

Diameter 7" 8"

Bearing S. 50° W. S. 47° E.

Distance 10 lks. 18 lks.

Do you believe this to be a genuine Land Office Corner? YES

If not, why? \_\_\_\_\_

R. O. T.


(Signature)

Dec. 1, 1922  
(Date)

8-7004 N-13  
(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 144 R. 26 S. 5th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

N-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. Mer.

Corner common to Sections

15 and 22

Corner consists of a (not) in place


State condition New treated post.

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No


If not, why? \_\_\_\_\_

Ray W. Jassett  
 (Signature)  
Sept 1953  
 (Date)  
 \_\_\_\_\_  
 (Title)

N-15

Set 7" treated post  $3\frac{1}{2}$  feet high and  
 sorbed "1/4 SCF". It is on a small  
 raise. A 6" birch bears N. 42 W. 0.44 ob.  
 A 6" birch bears S. 65° E. 0.29 ob. and  
 a 7" asp bears S. 33 W. 0.53 ob. This  
 is a U.S. established corner.  
 Gibbews

Corner again. Now treated post.  
 Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

N 15

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. Mer.

1/4

Corner common to Sections

15, and 22

Corner consists of a (not) in place


State condition New treated post.

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why?

*F. J. Smith*


(Signature)

53

(Date)

(Title)

(Make sketch of topography near Corner)



Actual Location Poster is on a

inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

Set 7' crested post 3 1/2 feet high and

marked "1/4 80". It is on a small

rise. A 6" iron bore S. 72 W. 0.47

A 6" iron bore S. 65° E. 0.29 ch. and

a 4" ash bore S. 33 W. 0.53 ch. This

is a P.S. established corner.

7-30-62 S.M.A.D.P. - P.S. -