

U. S. Department of Agriculture

FOREST SERVICE

N-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 N. R. 26 W. 5th Mer.

Sec. Corner common to Sections

14, 15, 22, and 23

Corner consists of a (not) in place



State condition New treated post

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? IR IN

Ray W. Fassett (Signature)

Sept 1953 (Date)

(Title)

N-17

Set 7" treated post 3/4 foot high from  
 which is on 1 1/2 red pine bears S. 73°  
 W. 0.45°. This is probably original GLO  
 location, as pine and spruce stumps fit  
 original calls for B.T.'s. Post scribbled  
 "30".

Corner again.  
 New treated post

Give any further facts which will aid in finding this

chains distant.

0.67

From which this Corner bears


N. 73 E.

side of

said tree

tree 1 1/2 inches diameter, on the east

Metal Location Poster is on a Red Pine



(Make sketch of topography near Corner)

T. 144 N. R. 26 W. Mer. N-17

U. S. Department of Agriculture

FOREST SERVICE

N-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N., R. 26 W., 5th Mer.

Sec. Corner common to Sections

14, 15, 22, and 23

Corner consists of a \_\_\_\_\_ (not) in place

State condition Not treated post

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*[Handwritten Signature]*

(Signature)

53


(Date)

(Title)

Set A treated post 3/4 foot high from  
which ~~is~~ on 1 1/2" red pine bears S. 73°  
W. 0.57'. This is probably original OIO  
location as pine and spruce stumps fit  
original calls for B. T. S. Post notched  
original calls for B. T. S. Post notched

Give any further facts which will aid in finding this  
Corner again.  
0.67

from which this Corner bears N. 73 E.  
side of  
tree 2 1/2 inches diameter, on the east  
Metal Location Poster is on a Red Pine  
said tree



(Make sketch of topography near Corner)