

U. S. Department of Agriculture

FOREST SERVICE

H-17

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 26 W. Mer.

1/4 Corner common to Sections 10, and 11

Corner consists of a (not) in place State condition New treated post.

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Grid for cardinal position with columns N, W, S, E

Grid for diagonal position with columns NW, SW, SE, NE

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Grid for sketching bearing trees and rocks

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Signature

(Signature)

Date

(Date)

(Title)

CORNER OF THE PUBLIC SURVEY

There were remains of old settled section of old wire fences to the N. and S. of the post 1/4 30", Post 1/4 at Inter-Set 7" treated post 3/4 feet high and Corner again.


Give any further facts which will aid in finding this corner chains distant.

From which this Corner bears

side of

three inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)