

U. S. Department of Agriculture

FOREST SERVICE

*Chippewa*

NATIONAL FOREST

123  
E-1  
P.

CORNERS OF THE PUBLIC SURVEY

T. *144* R. *27W & 28W* *5th* Mer.

Section

Corner common to Sections

*7*, *12*, *1*, and *6*

Corner consists of a *squared stake* (not) in place

State condition *Good*

Dimensions above ground *2 X 2" X 3.5'* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>R28 R27</i>			

Species *Oak*

Diameter *5"*

Bearing \_\_\_\_\_

Distance *25'*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Paul Moeller*

(Signature)

*Dec. 4, 1933*


(Date)

*Technical Foreman*

(Title)

X

Metal Location Poster is on a *small* tree *3* inches diameter, on the *East* side of ~~West corner~~ from which this Corner bears *5* chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 144 N. R. 28 W. & R. 27 W. S. 7 M. Mer.