

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

K-5

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 5<sup>th</sup> Mer.



1/16 Corner common to Sections  
17, and 18

Corner consists of a metal tag (---) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches.  
Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box  
and fill blanks below, giving bearings from Corner to Trees  
and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence


Stanley M. Morrison  
(Signature)

2-1-61  
(Date)

Forestry and  
(Title)

T. 144 R. 27 Mer. 5th

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *Bank*

tree *8* inches diameter, on the *East*

side of *the*

this Corner bears

(Bearing) and (Distance)

Section line marker between Secs. and is on

a (Tree, post, etc.) on the

(Name of road, trail, etc.) located

chains E, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again:

*W. 1/2 Sec. 2 E. of 17.*