

U. S. Department of Agriculture

FOREST SERVICE

0-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 27W 5th Mer.

416 Corner common to Sections
, , , and 20



Corner consists of a (not) in place
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why? No evidence

[Handwritten Signature]

(Signature)


A. J. DER

(Title)

4/16/16
(Date)

Corner again.
Blk like post. 1 S
W. of corner post. 1 S

Give any further facts which will aid in finding this
corner distant.
from which this Corner bears
side of
tree 11 inches diameter, on the East
Metal Location Poster is on a
Hard Maple



(Make sketch of topography near Corner)

T. 14 N. R. 27 W. 6th Mer.