

U. S. Department of Agriculture

FOREST SERVICE

CHIPPEWA NATIONAL FOREST

123
25-9

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 5 Mer.

Section ----- Corner common to Sections

8, 9, 17, and 16

Corner consists of a Wooden stake (not) in place

State condition rotten at ground line Guard

Dimensions above ground 24 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 144			
R 27			
S 17			

Species Ceder ceder ceder

Diameter 8 8 12

Bearing S25W S45 W S 20 E

Distance 23 31 25 links

Do you believe this to be a genuine Land Office Corner Yes.

If not, why? -----

W. A. Bill

(Signature)

7/9/34

(Date)

Chief of Party

(Title)

Forest Service Marker on Road I
Chain North of Corner.

Corner again.

Give any further facts which will aid in finding this


0.31 chains distant.

from which this Corner bears North 45 East

side of tree

tree 8 inches diameter, on the North East

Metal Location Poster is on a cedar



(Make sketch of topography near Corner)