

U. S. Department of Agriculture  
FOREST SERVICE

123  
E-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 5<sup>th</sup> Mer.

Sec. Corner common to Sections  
4, 5, 8, and 9

Corner consists of a 9" Cedar Tree (not) in place

State condition Right on Corner

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

W. L. S.

(Signature)

For Ranger

(Title)

4/18/28  
(Date)

Blazed S. lines in all 4 cardinal directions

Corner again.

Give any further facts which will aid in finding this


20 ft. ~~obscure~~ distant.

from which this Corner bears S. 34 W.

side of Tree

tree 6 inches diameter, on the W

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

T. 144 R. 27 Mer. 5th