

U. S. Department of Agriculture

FOREST SERVICE

Shippensburg NATIONAL FOREST

P-11

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 5th Mer.

1/4 Corner common to Sections

_____, _____, 21, and _____

Corner consists of a metal tag (_____) in place


State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS


METAL CORNERS



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No


If not, why? no evidence

Stanley M. Morrison
(Signature)

Forestry aid
(Title)

2-1-61
(Date)

(Make sketch of topography near Corner and show section line markers with "X")



Metal Location Poster is on a *corner*

tree *16* inches diameter, on the *E.*

side of *line* from which

this Corner bears *0* (Bearing) and *0* (Distance)

Section line marker between Secs. and is on

a *2* on the (Tree, post, etc.)

located chains *L, W, N, S,* from Sec. Cor.; $\frac{1}{2}$ Cor.; Whess Cor.

(Cross out nonapplicable)

Give any further facts needed to find Corner again:

Place line marker E. & N. of corner - corner marked C-27-78
corner by alignment by line down - line parallel
line E. & N. approx 10' from line