

Form 874-B—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

L-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 44 N R. 27 W 5<sup>th</sup> P. Mer.

1/4 Corner common to Sections  
 \_\_\_\_\_, \_\_\_\_\_, 15, and 16



Corner consists of a iron pipe (not) in place  
 State condition Good

Dimensions above ground 2" by 12" inches

Sketch grooves, letters, figures, or notches, on upper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen R. P.

Diameter 4 1/2" 2"

Bearing N 33° E S 41° W

Distance 7 1/2 Ls. 3 4 Ls.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

1/6/41  
 (Date)

(Signature)

U.S. DEPARTMENT OF AGRICULTURE


BUREAU OF LAND MANAGEMENT

NATIONAL FOREST

COMMISSION OF THE PUBLIC SURVEY

*Corner again.  
Give any further facts which will aid in finding this  
chain distant*

*From which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a  
Bog on Sect B.T.*



(Make sketch of topography near Corner)

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

2-13

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 19N. R. 27W. 5<sup>th</sup> P. Mer.

1/4 Corner common to Sections  
15, and 16.

Corner consists of a Iron Pipe (net) in place

State condition Good

Dimensions above ground 2" x 12" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4  
S. 15

1/4  
S. 16

B.T.

B.T.

Species Aspen R.P.

Diameter 4 1/2" 7"

Bearing N 33° E S 91° W

Distance .71 chs. .39 chs.

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? \_\_\_\_\_

E. M. Handy  
(Signature)

2/3/38  
(Date)


(Title)

U. S. Department of Agriculture

Location Poster on Joe Car-  
penter road is located about  
80 Kms. N. of this car.  
Corner again.

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of

Metal Location Poster is on a  
*(one on each bearing tree)*  
tree inches diameter, on the



(Make sketch of topography near Corner)