

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 5<sup>th</sup> Mer.1/4 Corner common to Sections  
22, and 27Corner consists of a W. B. Tree (not) in place  
State conditionDimensions above ground 14" D. B. H. inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NoIf not, why? The scribe was inCrayon and no original B.T'sRemain

R. O. T. W. L. S.

(Signature)

For Ranger

(Title)

12/20/27  
(Date)

Department of Agriculture

NATIONAL FOREST

COMMISSIONER OF THE PUBLIC SURVEY

Found  
Crayon K mark on it was  
but a 14' W.B. tree with a  
No corner stake was found  
Corner again.

Give any further facts which will aid in finding this


15 ft distant.

from which this Corner bears S. 35 E.

side of

tree 6 inches diameter, on the

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 144 R. 27 S. 74 Mer.