

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

3-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 199 N. R. 27 W. 5th P. Mer.

1/9 Corner common to Sections

10, and 15

Corner consists of a Iron Pipe (not) in place

State condition Good

Dimensions above ground 1 1/2 x 1 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>5/10</u>			
<u>B.T.</u>			

Species Larch

Diameter 8 1/2

Bearing N43°W

Distance .79 chs.

Do you believe this to be a genuine Land Office Corner? Yes.


If not, why? _____

E. M. Handy
(Signature)

1/27/38
(Date)

Semi-Skilled Wkr.
(Title)

Metal Location Poster is on a *large* side of *tree* from which this Corner bears *S 43° W 791 Ks.* chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 143N R. 27W Sth P. Mer.