

U. S. Department of Agriculture

FOREST SERVICE

19

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 27 W 5th Mer.

1/4 Corner common to Sections

23, and 26

Corner consists of a brass capped pipe (not) in place

State condition good

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	*	S	*

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 144 N
R 27 W
S. 23

B.T.

Species N. Pine

Diameter 18 in

Bearing N. 38° W

Distance 78 1/2

Do you believe this to be a genuine Land Office Corner?

If not, why?

1/9/41
(Date)

(Signature)

(Title)

U. S. DEPARTMENT OF THE INTERIOR

FOREST SERVICE

CORNER OF THE

Corner again.

Give any further facts which will aid in finding this

chain distant

from which this Corner bears

N 37° W


side of

tree 18 inches diameter, on the

South side

Metal Location Poster is on a

N 37° W



(Make sketch of topography near Corner)

T. L. N. R. 27 W. 5 E. Mer.