

U. S. Department of Agriculture  
FOREST SERVICE

N-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 27 W. 5 th. Mer.

1/4 Corner common to Sections  
14, and 23

Corner consists of a as on stake (not) in place  
State condition Fair

Dimensions above ground 3 ft. high inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

N	W	S	E

DIAGONAL POSITION

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

FSOP			

Species ASPEN  
Diameter \_\_\_\_\_  
Bearing S 10 W  
Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No  
If not, why? This is a cruisers corner  
and there is no evidense of a G.L.O.  
corner near it.

G. Gordon  
(Signature)  
Chief of party EM  
(Title)

(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this

..... chains distant.

31

from which this Corner bears


N 10 E

side of said trees

tree ..... inches diameter, on the North East

Metal Location Poster is on a Aspen

Cruisers Poster



(Make sketch of topography near Corner)

Form 874-B—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

N-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 27 W 5th Mer.



1/4 Corner common to Sections  
14, and 23

Corner consists of a brass capped pipe (not) in place  
 State condition good

Dimensions above ground \_\_\_\_\_ inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T144N R27W S 14			
B.T.			

Species None  
 Diameter 1 1/2"  
 Bearing N 10° E  
 Distance 3 1/2 links.

Do you believe this to be a genuine Land Office Corner? Yes  
 If not, why? \_\_\_\_\_

1/9/41 (Date)  
 \_\_\_\_\_ (Signature)  
 \_\_\_\_\_ (Title)

U.S. Department of Agriculture

FOREST SERVICE


FOREST SERVICE NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

Corner of a ...  
Corner again

Give any further facts which will aid in finding this  
chain's distance  
DIAGONAL POSITION

from which this Corner bears  
side of  
Inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)