

U. S. Department of Agriculture

FOREST SERVICE

23
E-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 5th Mer.

Sec Corner common to Sections 1, 2, 11, and 12

Corner consists of a Squared Sp. Tree (not) in place State condition

Dimensions above ground 6" x 26' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|----------------------------|--|--|--|
| T. 144 N. R. 27 W. 2 | | | |
| | | | |

Species J. Pine Poplar

Diameter 13" 14"

Bearing N. 71 W. N. 35 E.

Distance 44 lks. 38 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Dana F. Kirkman

(Signature)

Forest Ranger

(Title)

3/12/28
(Date)

U.S. Department of Agriculture

Car is about 5 chs. west of East edge of open SWAMP

Well Blazed lines to S, W & E. Corner again.


Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of Tree

tree 6 inches diameter, on the North

Metal Location Poster is on a Spruce Tree



(Make sketch of topography near Corner)

T. 14 N. R. 27 Mer. 6 1/4