

U. S. Department of Agriculture
FOREST SERVICE

N-22

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 Mer.

to Corner common to Sections
13, and 27

Corner consists of a wood post (not) in place
State condition pass

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *None*

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *None set.*

R. H. Christensen


(Signature)

1-16-58
(Date)

R. F. R.
(Title)

Corner again.
Mr. Charol 20 chs W of
1/2 13 + found old sq. post
on line. Marked by the post.
In 10 Ins. typew. line marked
with red paint to east.

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 144 R. 27 Mer.