

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27+28 5th Mer.

Meander on South Point of Corner common to Sections
Drumbeater Lake 25, and 30

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>T. 144 N.</u>			
<u>R. 27+28 W.</u>			
<u>S. 25-30</u>			

Species one Tam B.T.

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? found by Minn. State
For. Service.

C. B. Stott

(Signature)

3-15-28

(Date)

J. F.

(Title)

(Make sketch of topography near Corner)

Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 199N R. 27428W 5th P. Mer.
Sec. Corner common to Sections

25, 30, 31, and 36

Corner consists of a ~~corner~~ mon. (not) in place

State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T199
R28
S25

T199
R28
S36

T199
R27
S31

T144
R27
S36

BT

BT

BT

BT

Species Tam Tam Tam Tam

Diameter 9" 9" 9" 3"

Bearing N69W S29W S18E N80E

Distance 16.64s .294s .504s .314s

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. M. Anderson
(Signature)


11/27/38
(Date)

Supervisor
(Title)

Handwritten notes on a grid background, including the phrase "Well placed lines." written upside down.

Corner again.

Give any further facts which will aid in finding this chains distant, from which this Corner bears side of tree inches diameter, on the Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 199N R. 27E8W S4P. Mer.

U. S. Department of Agriculture
FOREST SERVICE

25

Chippewa NATIONAL FOREST


CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 27 & 28 W 5th. P Mer.
Sec.

Corner common to Sections
30, 31, 25, and 36

Corner consists of a concrete mon. (not) in place
State condition good

Dimensions above ground 6" dia. inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 144 N R 28 S 25	T 144 R 28 S 36	T 144 R 28 S 30	T 144 R 27 S 31
BT	BT	BT	BT

Species	<u>Tam.</u>	<u>Tam.</u>	<u>Tam.</u>	<u>Tam.</u>
Diameter	<u>4"</u>	<u>4"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N64W</u>	<u>S29W</u>	<u>N80E</u>	<u>S18E</u>
Distance	<u>16 chs.</u>	<u>29chs.</u>	<u>31chs.</u>	<u>50chs.</u>

Do you believe this to be a genuine Land Office Corner? Yes.
If not, why? _____

G. M. Hardy
(Signature)

12-14-38

(Date)

(Title)

U. S. DEPARTMENT OF AGRICULTURE


NATIONAL FOREST

CORNER OF SECTION 25 AND 30

Corner again: Range line is well placed.

Give any further facts which will aid in finding this chain distant.

from which this Corner bears side of tree inches diameter, on the Metal Location Posters on a



(Make sketch of topography near Corner)