

U. S. Department of Agriculture

FOREST SERVICE

AS 22

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 27 S² Mer.

1/32 Corner common to Sections

25, _____, _____, and _____

Corner consists of a metal lg (rod) in placeState condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? YesIf not, why? No evidence

S. M. Morrison

(Signature)


Forest Officer

(Title)

3/30/59
(Date)

Corner again.
Mr. J. S. Jones
& Sons from corner

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of *W. or*
tree *9* inches diameter, on the *East*
Metal Location Poster is on a *Beam*



(Make sketch of topography near Corner)

T. 144 R. 27 S. 2 Mer.