

U. S. Department of Agriculture
FOREST SERVICE

R-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 28 5th Mer.

1/4 Corner common to Sections

20, and 29

Corner consists of a wood stake (not) in place

State condition Fair

Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

F.S.L.P.			

Species W. Pine _____

Diameter 6 _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? there are no bearing trees and stake is not scribed.

C. Gordon

(Signature)

Chief of Party

(Title)

(Date)

Section 36

Section 36

Section 36

Section 36

Corner again.

Give any further facts which will aid in finding this


SH. 1/4 section distant.

from which this Corner bears N 33 E

side of said tree

tree 6 inches diameter, on the N.W.

Metal Location Poster is on a W. 1/4



(Make sketch of topography near Corner)