

U. S. Department of Agriculture  
FOREST SERVICE

U-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 28 5th P. Mer.

fifteenth 5116 Corner common to Sections  
26 and 27

Corner consists of a yellow tin (not) in place  
State condition gone

Dimensions above ground 54 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? no


If not, why? no evidence found

1/26/59 (Date) Martin K. Lauritzen (Signature) Asst. Dist. Fore Ranger (Title)

U-17

Corner again.  
 Map printed in blue - 100 ft. long  
 Marked with green set corner  
 S 26/27, 34, 35 in blue  
 N 41 E.

Give any further facts which will aid in finding this  
 station distant.  
 from which this Corner bears  
 side of  
 tree 6 inches diameter, on the  
 Metal Location Poster is on a  
 Black Sparrow



(Make sketch of topography near Corner)

T. 144 R. 28 Mer. 1904