

L-1

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29030W ^{5th} Mer.

Corner common to Sections 13, 18, and _____



Corner consists of a Iron stake brass cap (not) in place
State condition Good

Dimensions above ground 12 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Clear Maple Maple _____

Diameter 15 14 _____

Bearing N 82 E S 55 W _____

Distance 16 ft 30 ft _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

D. R. Bower

Signature

Estimator

Dec. 2, 1930


Date.

Title.

L-1 3087

Northwood Swamp

Corner again
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner.) 8-3027

T. 14411 R. 29 & 30 W. 1-1 Mer.