

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W ^{30W} 5th Mer.

1/4 Corner common to Sections
1, 6, and _____



Corner consists of a Iron pipe - has cap (not) in place
State condition _____

Dimensions above ground 8" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4
56

1/4
51

BT

BT

Species Cedar Cedar _____

Diameter 7" 8" _____

Bearing N31E N56W _____

Distance 7' 8' _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

D. B. Hoover

Signature

12/29/30

Date

O. Tolson


Title. C-1 8-3027

(Make sketch of topography near Corner.)

Mer.

R. 29 W + 30 W

T. 14 N



Metal Location Poster is on a

tree _____ inches diameter, on the

side of _____

from which this Corner bears _____

_____ chains distant.

Give any further facts which will aid in finding this

Corner again.

Handwritten signature