

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Y-3

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 29 W 5th Mer.

CS 1/16 Int. Corner common to Sections 31, _____, and _____

Corner consists of a IRON POST (not) in place

State condition Good

Dimensions above ground 8 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>CS 1/16</u> <u>531</u>			
<u>13 T</u>			

Species SPEN
Diameter 6
Bearing N52E
Distance 40 F

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

O. R. Bauer

Signature

Estimator

Dec. 8, 1930


Date

Title

Y-3

T. 144 N. R. 29 W. 5th Mer. 3

9-2027 (Make sketch of topography near Corner.)



Metal Location Poster is on a

tree _____ inches diameter, on the

side of _____

from which this Corner bears _____

chains distant.

Give any further facts which will aid in finding this

Corner again.