

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*posted*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144N* R. *29W* S. *5* Mer.  
 Sec. *31* Corner common to Sections  
*31*, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a *IRON POST* (~~not~~) in place  
 State condition *900 &*

Dimensions above ground *10* inches.  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>C<sup>1</sup>/<sub>4</sub></i> <i>S31</i>	<i>C<sup>1</sup>/<sub>4</sub></i> <i>S31</i>		
<i>BT</i>	<i>BT</i>		

Species *Redwood Maple*  
 Diameter *12"* *6"*  
 Bearing *S21E* *N5E*  
 Distance *36 FT.* *10 FT.*

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_  
 If not, why? \_\_\_\_\_

*O. R. Boerner*  
 Signature

Estimator

*Dec. 8, 1930*  
 Date.

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner again.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a

	Sec.		Sec.
	Sec.	31	Sec.