

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*P.S*  
*posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 29 W 5 Mer.

1/4 Corner common to Sections

19, and 20

Corner consists of a Iron Post + Brass Cap. (■) in place

State condition Good

Dimensions above ground 12 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 20

1/4 S 19

BT

BT

Species W. Pine Maple

Diameter 6 1/2 in 12

Bearing S 51 E N 15 E

Distance 38 links 66 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*W. J. Adams*


Signature.

*Estimator*

10/17/30

Date.

Title. P.S 3027



8-3027 (Make sketch of topography near corner.)

T. 144 N. R. 29 W. Mer. 5

Metal Location Poster is on a *Balsam* tree 3 inches diameter, on the *E* side of *Sec 19* from which this Corner bears *S 58 E* 10 FT. ~~chains~~ distant. Give any further facts which will aid in finding this Corner again. *1 1/2 chains from Road*