

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 29 W 5<sup>th</sup> Mer.

Section Corner common to Sections  
7, 8, 17, and 18

Corner consists of a metal stake Brass cap in place  
State condition good

Dimensions above ground 12" inches.


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T144N R29W S8
---------------------

T144N R29W S17
----------------------

T144N R29W S18
----------------------

T144N R29W S7
---------------------

B.T.
------

B.T.
------

B.T.
------

B.T.
------

Species Balsam Maple Box Maple

Diameter 8" 12" 10" 9"

Bearing E31°N S30°E S26°W W27°N

Distance 27LKs 26LKs 20LKs 42LKs

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_


E. J. Juntunen  
Signature.

11/8/30  
Date.

O. O. P.  
Title.

T. 144N R. 29W  
Mer

8-8027 (Make sketch of topography near Corner.)



Metal Location Poster is on a *Maple*

tree *12* inches diameter, on the *S*

side of *Stake*

from which this Corner bears *S 30° E*

*at LK's* ~~owns~~ distant.

Give any further facts which will aid in finding this Corner again.