

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Chippewa NATIONAL FOREST *Posted*

CORNERS OF THE PUBLIC SURVEY

T. *144N* R. *79W* *5th* Mer.

Sec. Cor Corner common to Sections

7, 8, 6, and 5

Corner consists of a *wooden stake* (not) in place

State condition *interior two legs*

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<i>6</i>	<i>7</i>	<i>8</i>	<i>5</i>
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>v</i>			
<i>v</i>			

Species *Cedar*

Diameter *13*

Bearing *W*

Distance *5'*

Do you believe this to be a genuine Land Office Corner? *Yes*


If not, why? _____

12/23/30
Date.

Q. R. Borner
Signature
Estimator
Title. F-5 8027

T. ~~44~~ N. R. 29 W. S. 5 E. Mer.

8-3027 (Make sketch of topography near Corner.)



Metal Location Poster is on a _____
 tree _____ inches diameter, on the _____
 side of _____
 from which this Corner bears _____
 _____ chains distant.

Give any further facts which will aid in finding this
 Corner again.

In Cedar Grove
 growing on Cedar
 has been partly
 destroyed

E-5

copied
&
Pasted
5/6

U. S. Department of Agriculture
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 Mer. 5

Corner common to Sections

5, 6, 7, and 8

Corner consists of a 5" cedar stake (not) in place
scratched 5 on 4 sides other marks obliterated
State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____


(Signature)

(Date)

(Title)

E-5

(Make sketch of topography near Corner)



Metal Location Poster is on a _____
 tree _____ inches diameter, on the _____
 side of _____
 from which this Corner bears _____
 _____ chains distant.

Give any further facts which will aid in finding this
 Corner again.

18" Cedar Trees on Sec. 7
 dated J. N. 29 W. S. 7

No other Bearing Trees
 in evidence.