

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W 5<sup>th</sup> Mer.

Corner common to Sections  
17, 20, 1/16 and


Corner consists of a Iron stake, Brass <sup>cap</sup> in place  
State condition Good

Dimensions above ground six (6) inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

W 1/16  
S 20

W 1/16  
S 17

[Empty box]

[Empty box]

B.T

BT

[Empty box]

[Empty box]

Species Cedar Cedar

Diameter 12" 7"

Bearing E 13° N W 20° S

Distance 51 (links) 68 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Russell Willis

Signature.

Nov 10, 1930

Date.


Computer

Title. N-6 8-3027

T. 144N. R. 29W. 5th Mer.

8-2037

(Make sketch of topography near corner.)



Metal Location Poster is on a Yellow Birch tree 13 inches diameter, on the NW side of Stake from which this Corner bears N 14° E 37 k~~2~~ distant. Give any further facts which will aid in finding this Corner again.

Center of corner  
Swamp