

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 29 W 5 Mer.

1/4 Corner common to Sections

17, and 20

Corner consists of a Iron Post + Brass Cap (not) in place

State condition Good

Dimensions above ground 11 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4 5 17</u>

<u>1/4 5 20</u>

--

--

<u>B.T.</u>

<u>B.T.</u>

--

--

Species Cedar Balsam

Diameter 6 8

Bearing N55E S11E

Distance 41 LKS 25 LKS

Do you believe this to be a genuine Land Office Corner? yes


If not, why? _____

W. J. ...
Signature

Estimator
Title

11/21/30
Date

(Make sketch of topography near corner.)



Metal Location Poster is on a *Balsam*

tree *5* inches diameter, on the *S*

side of *Corner*

from which this Corner bears *S 5 W*

4 links *shans* distant.

Give any further facts which will aid in finding this

Corner again.

About 12 chs from Rd. g. E.