

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

*Copied & Posted
5/36
R-9*

NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 Mer.

Corner common to Sections
20, 21, 28 & 29, and

Corner consists of a new post (not) in place

State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

(Signature)

(Date)

(Title)

R-9

U.S. DEPARTMENT OF AGRICULTURE

U.S. DEPARTMENT OF AGRICULTURE

U.S. DEPARTMENT OF AGRICULTURE

U.S. DEPARTMENT OF AGRICULTURE

one old B I for 188, 29 others gone
Corner again.


Give any further facts which will aid in finding this
chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

R-9 Mer.

R. Mer.

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14th N R. 29 W 5 Mer.Sec. Cor. Corner common to Sections20, 21, 28, and 29Corner consists of a Iron Post + Brass Cap (not) in placeState condition goodDimensions above ground 5 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

N	W	S	E

DIAGONAL POSITION

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T144N
R29W
S 28

T144N
R29W
S 20

--

--

BT

B.T.

--

--

Species Maple W. PineDiameter 7 12Bearing S 28 E S 88 WDistance 68 LKS 85 LKSDo you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

W. J. Adams

Signature.


Inspector11/24/30

Date.

Title. R-9 8-3027

(Make sketch of topography near corner.)

T. 14 N. R. 29 W. Mer. *G*



Metal Location Poster is on an *H.S.L.*

tree *6* inches diameter, on the *E*

side of *SEC-COR*

from which this corner bears *S 75 E*

8 LKS chains distant.

Give any further facts which will aid in finding this

Corner again.

In 14th Twp. E.