

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

*posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 Mer.

Section Corner common to Sections

8, 9, 17, and 16

Corner consists of a Iron stake Brass cap (not) in place

State condition good

Dimensions above ground 12" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<u>T144N</u> <u>R29W</u> <u>S8</u>	<u>S17</u>	<u>S16</u>	<u>S9</u>
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T144N  
R29W  
S16

Rotted  
S17

B.T.

Species ELM ELM

Diameter 7" 12"

Bearing E12°S N55°S

Distance 61 Links 79 Links

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_

E. J. Juntunen  
Signature.

11/7/30  
Date.

C. O. P.  
Title. J-9



Metal Location: Poster is on a Aspen tree 17 inches diameter, on the NE side of stake from which this Corner bears 46 links ~~or more~~ distant.

E 26° N

Give any further facts which will aid in finding this Corner again.