

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W 5th Mer.

Section

Corner common to Sections

9, 10, 15, and 16

Corner consists of a IRON stake Brass cap (not) in place

State condition Good

Dimensions above ground 12" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<u>T144N</u> <u>T29W</u> <u>S9</u>	<u>S16</u>	<u>S15</u>	<u>S10</u>
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T144N
T29W
S15

T144
S

NR29
S
DOWN

T144N
T29W
S10

B.T.

B.T.

Species W. OAK

W. OAK

Aspen

W. OAK

Diameter 11"

11"

10"

Bearing E 8° S

E 8° N

S 35° W

N 16° W

Distance 40 LINKS

65 LINKS

18 L.

81 LINKS

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

E. J. Juntunen

Signature.


C. O. P.

7/7/80
Date.

Mer.

T. 24 N. 29 W.

(Make sketch of topography near corner.)



Metal Location Poster is on a *Aspen*

tree *12* inches diameter, on the *E*

side of *stake*

from which this Corner bears *N 50 S*

16 ~~feet~~ *feet* distant.

Give any further facts which will aid in finding this

Corner again.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

173

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W S 16 Mer.

SECTION

Corner common to Sections

9, 10, 15, and 16

Corner consists of a iron pipe in place

State condition Good

Dimensions above ground 12" high

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 144N R 29W S 15

T 144N R 29W S 16

T 144N R 29W S 16

B.T.

B.T.

B.T.

Species OAK, OAK, ASPEN, DOWN.

Diameter 10, 8, 12

Bearing S 75W, N 10W, S 60W

Distance 40, 80, 20

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why?

H. HANSON

(Signature)

1/9/36

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

N 89° E.

side of


Tree

tree 12 inches diameter, on the

EAST

Metal Location Poster is on a

ASPER



(Make sketch of topography near Corner)

T. HAN R. 29W J-13 Mer.