

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 29 W. Mer.

NW 1/16 Corner common to Sections  
11, and

Corner consists of a Iron pipe (not) in place  
State condition Good

Dimensions above ground 12" high inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

			<u>NW 1/16</u> <u>5 11</u>				
N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>NW</u> <u>1/16</u> <u>5 11</u>		<u>NW</u> <u>1/16</u> <u>5 11</u>	
<u>B.T.</u>		<u>B.T.</u>	

Species W. pine Oak

Diameter 6" 5"

Bearing N. 71° W N 80° E

Distance 30 Ls. 14 Ls.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_


H. Hanson  
(Signature)

1/7/36  
(Date)

(Title) F-18

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
CORNER LOCATION POSTER

Metal Location Poster is on a *White Pine* tree *5* inches diameter, on the *Tree* side of from which this Corner bears *N 14° W* *1875* feet, chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W. Mer.

NW 1/16 Corner common to Sections

11, and

Corner consists of a IRON PIPE. (not) in place


State condition Good

Dimensions above ground 12" high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W.P.I.R. Oak.

Diameter 6" 5"

Bearing N. 71° W N 80° E

Distance 30 Links 14 Links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?


H. HANSON. (Signature)

1/7/36. (Date)

(Title)

Corner again.  
 Re-located 20 4/21/18 by J. W. ...  
 & R. Jones - Mrs. ...  
 S.W. of corner

Metal Location Poster is on a **White Pine** tree **5** inches diameter, on the **North** side of **Tree** from which this Corner bears **N 14° W** **18 Links** or there abouts distant.  
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 144N R. 29W. Mer. F-18