

*Dec 1936*  
*Proved*

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W Mer.  
W 1/16 Corner common to Sections  
2, and 11

Corner consists of a Iron pipe (not) in place  
State condition Good

Dimensions above ground 12" high inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
			<u>W 1/16</u>	<u>S 2</u>			
N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>W 1/16</u>			
<u>S 11</u>			
<u>B.T.</u>			

Species Aspen  
Diameter 14"  
Bearing S 82° E  
Distance 27 1/2


Do you believe this to be a genuine Land Office Corner? yes  
If not, why? \_\_\_\_\_

H. Hanson  
(Signature)

1/7/36  
(Date)

Give any further facts which will aid in finding this corner again.

Metal Location Poster is on a tree 4 inches diameter, on the side of from which this corner bears 5 links chains distant. 560 ft. Tree S.E.



(Make sketch of topography near corner)

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

E-18

123

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W. Mer.

W 1116

Corner common to Sections

2, and 11

Corner consists of a iron pipe in place


State condition Good

Dimensions above ground 12" high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION

N	W	S	E	NW	SW	SE	NE		



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

W 116 S 111			
D.T.			

Species ASPEN

Diameter 14"

Bearing S 82° E

Distance 27 LINKS

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? \_\_\_\_\_

H. HANSON

(Signature)

1/7/36.

(Date)

(Title)

Corner again.  
Re-visited 4/2/51 R  
J. Morrison & R. F. Taylor  
upon road

Give any further facts which will aid in finding this

SKINKS  
skinks distant.

from which this Corner bears


560° E

side of Tree

tree 4 inches diameter, on the

ASPEN

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 144 N R. 29 W. Mer. E-18

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

E-18

*posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 5 Mer.



W 1/4 Corner common to Sections  
2, 11, and

Corner consists of a Iron stake (not) in place  
State condition good

Dimensions above ground 11 inches.  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen \_\_\_\_\_  
 Diameter 15" \_\_\_\_\_  
 Bearing E \_\_\_\_\_  
 Distance 18' \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_


R Willis  
Signature.

Estimator  
Title.

12/16/30  
Date.

Metal Location Poster is on a \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner.)

T. 144 R. 29 S. 5 E-18 Mer.