

U. S. Department of Agriculture

FOREST SERVICE

copied & posted 7/36

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 Mer. 5
1/4 Corner common to Sections

11, and 14

Corner consists of a New Post (not) in place
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

(Signature)


(Date)

(Title)

J-19

Corner again.
 Ave cedar @ T. 1, 011 1/2
 15 ft on S. 10 ft

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. R. Mer.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 Mer.

1/4 Corner common to Sections
 _____, _____, 11, and 14

Corner consists of a Iron pipe (not) in place
 State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

			$\frac{11}{4S}$	$\frac{11}{14}$				
N	W	S	E	NW	SW	SE	NE	

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{11}{4S}$			
B.T.			

Species cedar _____

Diameter 7 in. _____

Bearing N. 16° W _____

Distance 0.15 ch. _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Friesen
 (Signature)

1/10/36
 (Date)

(Title) J-19

Corner again.

Give any further facts which will aid in finding this

0.17 chains distant.

from which this Corner bears

S. 11.° E

side of


Tree

tree

6 inches diameter, on the North

Metal Location Poster is on a

Cedar



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

J-19

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 Mer.

1/4 Corner common to Sections

11, and 14

Corner consists of a Iron pipe in place

State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E	NW	SW	SE	NE	

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S			
B.T.			

Species CedarDiameter 7 in.Bearing N. 16° W.Distance 0.15 chs.Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

Friesen

(Signature)

1/10/36

(Date)

(Title)

J-19

Corner again. No. 6-23-01 by J. Williams - form 5282-12

Metal Location Poster is on a cedar tree 6 inches diameter, on the North side of T. 144 R. 29 from which this Corner bears 0.17 chains distant. Give any further facts which will aid in finding this

	Sec. 4		
		1/4 S.	
	Sec. 1		

(Make sketch of topography near Corner)

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144N* R. *29W* Mer.

Corner common to Sections *11*, *14*, and

Corner consists of a *wooden post* (not) in place
State condition *worn*

Dimensions above ground *3'* inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>11</i>		<i>14</i>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/45</i>			
<i>13T</i>			

Species *Cedar*
Diameter *7*
Bearing *N84W*
Distance *8*

Do you believe this to be a genuine Land Office Corner? *Yes*
If not, why? _____

O. R. Brewer
Signature.
Estimator
Title.

12/17/30
Date.

Johnson

Corner again.

Give any further facts which will aid in finding this

chains-distant.

left

from which this Corner bears

S 35 E


side of

inches diameter, on the

SW 53

Metal Location Poster is on a

chain



(Make sketch of topography near Corner.)

T. LEAH N. R. 29W

53

J-19 Mer.