

U. S. Department of Agriculture  
FOREST SERVICE

CHIPPENAW NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 29 W. 5 Mer.

1/16 Corner common to Sections  
\_\_\_\_\_, \_\_\_\_\_, and 14

Corner consists of a 1.00 pipe (not) in place  
State condition good

Dimensions above ground 1.5" x 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

SE			
1/16			
S 14			
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SE 1/16 S 14	SE 1/16 S 14		
BT	BT		

Species W. Spruce Maple

Diameter 10" 9"

Bearing N 16 W S 4 E

Distance 25 lks. 19 lks.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

E. M. Handy  
(signature)

C. O. P.  
(Title)

(Date)

Give any further facts which will aid in finding this corner again.

from which this corner bears \_\_\_\_\_ chains distant.

<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec. 14</p>	<p>Sec.</p>

(Make sketch of topography near corner)

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 29 W. 5 th. Mer.

1/16 Corner common to Sections  
, and 14

Corner consists of a iron pipe (not) in place

State condition good

Dimensions above ground 1.5" by 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

SE 1/16 S14			
-------------------	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SE 1/16 S 14
--------------------

SE 1/16 S 14
--------------------

--

--

BT
----

BT
----

--

--

Species W. Spruce Maple

Diameter 10" 9"

Bearing N16W S44E

Distance 25 lks. 19 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

E. J. Handy

(Signature)


Chief of party

(Date)

(Title)

Corner again.

Metal Location Poster is on a tree..... inches diameter, on the side of..... from which this Corner bears..... chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 5th Mer.

SE 1/16 Corner common to Sections X, X, X, and 14

Corner consists of a 17oz pipe (not) in place State condition good

Dimensions above ground 1.5" x 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

SE			
1/16			
S. 14			
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SE
1/16
S. 14

SE
1/16
S. 14



B.T.
------

B.T.
------

--

--

Species W. Spruce Maple

Diameter 10" 9"

Bearing N 16 W S 44 E

Distance 25 lks 19 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

E. M. Handy

(Signature)


Chief of Party

(Title)

(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T 144 R 28  
 Mer. 51M-20