

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *124 N* R. *29 W* Mer.

N 1/6
----- Corner common to Sections
13 -----, *14* -----, and -----

Corner consists of a *Iron stake - Brass cap* (not) in place
State condition *Good*

Dimensions above ground *10* inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>13</i>			<i>14</i>
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

N 1/6
5124

N 1/6
513

13 T

13

Species *ASPEN* *11 B. S.* -----
 Diameter *5"* *12"* -----
 Bearing *S 62 W* *S 56* -----
 Distance *25* *60* -----

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? -----

O. R. Berner


Signature

Estimator

Title. **K-21** 3027

12/15/30
Date.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



9-3027 (Make sketch of topography near Corner.)

T 144N R. 29W
 Mer. K-21

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 Mer. 5

N 1/6 Corner common to Sections

13, 14, and _____

Corner consists of a Iron stake (~~not~~) in place

State condition good

Dimensions above ground 6" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>N 1/6</u>
<u>314</u>

<u>N 1/10</u>
<u>513</u>

--

--

<u>BT</u>

<u>BT</u>

--

--

Species Aspen NR Pine

Diameter 7" 13"

Bearing S 66° E S 30° W

Distance 15 55'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

R Willis

Signature.

Estimator

Title. K21 8-3027

12/13/10

Date.

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.
13		14	

9-3027 (Make sketch of topography near Corner.)

T. 144 R. 29 S. Mer. K-21