

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 144N R. 29W Mer.

1/16 Corner common to Sections  
1, and 12

Corner consists of a 1.007 PIPE (not) in place  
State condition Good

Dimensions above ground 12" high inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
N	W	S	E	NW	SW	SE	NE
			E 1/16	S 12			

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E 1/16 S 12		E 1/16 S 12	
B.T.		B.T.	

Species L. Pine Maple  
Diameter 9" 6"  
Bearing N 84° W S 45° E  
Distance 19 lks. 34 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

H. Hanson  
(Signature)


1/15/36  
(Date)

(Title) E-24

Corner again

Give any further facts which will aid in finding this

831/3  
 From which this Corner bears  
 side of Tree  
 tree 8 inches diameter, on the South  
 Metal Location Poster is on a Norway Pine  
 S. 170 E



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

E-24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 29 W. Mer.

1116 Corner common to Sections

1, and 12

Corner consists of a IRON PIPE (not) in place

State condition GOOD

Dimensions above ground 12" high

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION

			E 1116 S1 S12					
--	--	--	------------------	--	--	--	--	--

N W S E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E 1116 S1		E 1116 S12	
B.T.		B.T.	

Species PINE Maple

Diameter 9" 6"

Bearing N 84° W S 43° E

Distance 19 LINKS 34 LINKS

Do you believe this to be a genuine Land Office Corner? YES

If not, why?

H. HANSON (Signature)

1/15/36 (Date)

(Title)

E-24

Corner again.

Give any further facts which will aid in finding this


23.145. ~~corner~~ distant.

from which this Corner bears 517.6

side of ~~tree~~ *tree*

tree 8 inches diameter, on the South

Metal Location Poster is on a Norway Pine



(Make sketch of topography near Corner)

T. 144 N. R. 29 W. Mer.

E-24