

U. S. Department of Agriculture  
FOREST SERVICE

*Posted*  
*R3*

*Chipewah* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144N* R. *30W* *5<sup>th</sup>* Mer.

*1/4* Corner common to Sections  
*30*, and *19*

Corner consists of a *Dr. capped pipe 1"* (not) in place  
State condition *good*

Dimensions above ground *2"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/4</i> <i>319</i>	<i>1/4</i> <i>319</i>			
<i>BT.</i>	<i>BT.</i>			

Species *B. P. Oak* *W. Pine*

Diameter *10"* *16"*

Bearing *N52°15'E* *N47°30'W*

Distance *7 1/2* *120 1/2*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? .....

*Wm B. Rose*

(Signature)

*COMMISSIONER*

(Title)

*8/23/34*  
(Date)

9530  
519

Corner again.

Give any further facts which will aid in finding this


7 1/2 chains distant.

from which this Corner bears S52°15'W

side of The Tree

tree 10 inches diameter, on the S.W.

Metal Location Poster is on a Black Rock



(Make sketch of topography near Corner)

T. 794N R. 30W Mer. R-3