

U. S. Department of Agriculture

FOREST SERVICE

posted

Chippewa NATIONAL FOREST N3

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 5 Mer.

Corner common to Sections 18, and 19


Corner consists of a (not) in place State condition Good

Dimensions above ground 7 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N

W

S

E

NW

SW

SE

NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

4519

4519

107

107

Species w/cor w/cor

Diameter 3" 4"

Bearing S 65 W 25 W

Distance 48 43 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

17

N 55° W

side of

Woods road

tree 31 inches diameter, on the

West

Metal Location Poster is on a

White Oak

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. LEWIS R. 37 1/2 N-3 Mer.