

A-3

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

A3

CORNERS OF THE PUBLIC SURVEY

T. *144N.* R. *30W* Mer. *57N*

Quarter Corner common to Sections
6, and *North side*

Corner consists of a *Grass Rapid Pipe (not)* in place
State condition *Good*

Dimensions above ground *12* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/4 S. 6.</i>			
<i>B.T.</i>			

Species *W. Oak*

Diameter *6"*

Bearing *S. 67° E*

Distance *16 1/2*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____


J. A. G. Eltham
(Signature)

Tech. Eng.
(Title)

8/20/24
(Date)

A-3

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T 199 R 30 Mer. A-3