

W-5

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

WS

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 30W 5th Mer.

Sixteenth #3 Corner common to Sections

31, and 32

Corner consists of a Br. cap. 1" iron pipe in place
State condition good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

N 1/16			
S 31			
BT			

Species Birch

Diameter 10"

Bearing S 71° 30' W

Distance 361k

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Dorman J. Sutton
(Signature)

10-9-34
(Date)


Compassman
(Title)

W-5

Metal Location Poster is on a *None*

tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 144N R. 30W 5th Mer W-5