

V-5

U. S. Department of Agriculture  
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

V5

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 30W 5<sup>th</sup> Mer.

Section Corner common to Sections

29, 30, 31, and 32

Corner consists of a Br. cap 1" pipe ( ~~not~~ ) in place

State condition good

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T144N  
R30W  
S29

S31

Orig  
B.T.

B.T.

B.T.

Species Elm Birch W. Pine

Diameter 19" 7" Shump

Bearing N40°15'E S15°W N55°W

Distance 29.1k 44.1k 61.1k

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Dorman J. Sutton

(Signature)

10-9-34  
(Date)

Compassman

(Title)

V-5

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears **548.15'E**

side of **tree**

tree **19** inches diameter, on the **SW**.

Metal Location Poster is on a **Elm**



(Make sketch of topography near Corner)

T. 144N R. 30W 5th Mer. V-5