

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

L-5

CORNERS OF THE PUBLIC SURVEY



T. *144N* R. *30W* *5th* Mer.

Quarter Corner common to Sections
17, and *18*

Corner consists of a *Br. cap. 1" iron pipe* in place
State condition *good*

Dimensions above ground *8* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4
S 17

1/4
S 18

B.T.

B.T.

Species *W. Oak* *Aspen*

Diameter *10"* *12"*

Bearing *S 59° 45' E* *S 53° 15' W*

Distance *66 1/4* *49 1/4*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Dorman J. Sutton

(Signature)

Campesman

(Title)

9-5-34
(Date)

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

from which this Corner bears *N. 59° 15' W.*

side of *tree*

tree *.12"* inches diameter, on the *north west*

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. 144 N. R. 90 W. 5th Mer. T-5