

U. S. Department of Agriculture
FOREST SERVICE

R-7
R-1
Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 30W 5th Mer. Quarter
Corner common to Sections

20, and 29

Corner consists of a Br. cap. 1" pipe (not) in place
State condition good

Dimensions above ground 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>S20</u>			
<u>B.T.</u>			

Species W. Birch

Diameter 6"

Bearing N71 1/4° W

Distance 107

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Dorman J. Sutton

(Signature)

Compassman

(Title)

9-19-34
(Date)

R-7

Corner again.

Give any further facts which will aid in finding this


16 1/2 chains distant.

from which this Corner bears *N 49° E*

side of *tree*

tree *4* inches diameter, on the *NW*

Metal Location Poster is on an *Aspen*



(Make sketch of topography near Corner)

T. 144N R. 30W 5th Mer. R-1