

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

E7

CORNERS OF THE PUBLIC SURVEY

T. 144N. R. 30W Mer. 579

Quarter Corner common to Sections
5, and 8


Corner consists of a Brass Capped Pipe in place
State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 38

1/4 5

BT

BT

Species EMM W. Pine

Diameter 8" 8"

Bearing S. 66° W. N. 15° E.

L10 Distance 44 1/4 39 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. P. Gjelhaug

(Signature)

Tech. Eng.

(Title)

10/26/34

(Date)

Dotted lines for writing.

Corner again.

Give any further facts which will aid in finding this


..... chains distant. 0.07

from which this Corner bears North

side of 700

tree 8 inches diameter, on the North

Metal Location Poster is on an Elm



(Make sketch of topography near Corner)