

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

T-9

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 30 W 5th Mer.

Corner common to Sections 28, and 29

Corner consists of a Brass Iron Pipe (not) in place
State condition Good

Dimensions above ground 7" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 144 N R. 30 W Sec. 28	T. 144 N R. 30 W, SEC 29	Sec 28	
B.T.	B.T.	BT	

Species B. SPRUCE B. SPRUCE B. SPRUCE
 Diameter 6" 6" 4"
 Bearing N 103° 0' W N 90° 30' W N 76° 20' E
 Distance 13 1/2 13 1/2 25

Do you believe this to be a genuine Land Office Corner? Yes
If not, why?

C. R. DuBois

(Signature)

COMPASS MAN

(Title)

19-5-34

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant. 0.137

from which this Corner bears S 40° 30' E

side of T&E

tree 6 inches diameter, on the S.E.

Metal Location Poster is on a BACK SPACE



(Make sketch of topography near Corner)

T/44 N R. 30 W S.E. 79 Mer.